

Add iPod Capability to Your Factory Radio



Owner's Manual PXDP SoundByte

iSimple Solutions®,
A division of AAMP of America™
13160 56th Court Clearwater, Florida 33760
Ph. 866-788-4237
support@isimplesolutions.com
©2009 AAMP of Florida, Inc.

Table of Contents

	Pages
CHAPTER 1-Getting Started	
1.1 Introduction	4
1.2 Precautions	4
1.3 Configuration & Harnesses	5
1.4 Programming the PXDP	6
CHAPTER 2-General Installation	
2.1 Installation Location	7
2.2 Pre-Installation Checklist	8
2.3 Wiring Connections	8
2.4 Installation at Changer Location	10
2.5 Installation at Radio	11
CHAPTER 3 -Operation	
3.1 Operation	13
3.2 Troubleshooting	15
3.3 Warranty	16
3.4 Warning	16
3.5 FCC Statement	17
Dipswitch Settings & Harness Guide	18


PXDP Connections



Factory Radio (not included)



Vehicle Specific Harness (actual harness may vary)



PXDP Interface



Chapter 1- Getting Started

1.1 Introduction

Thank you for purchasing the PXDP iPod Interface, by iSimple®. The PXDP is designed to provide endless hours of listening pleasure through most vehicles' factory radios. To ensure that your iPod performs correctly in your car or truck, we recommend that you read this entire manual before attempting installation of the PXDP interface. The PXDP interface will allow you to connect your iPod to a factory radio that has the ability to control a CD changer. The PXDP is designed to be used with most iPod Models featuring the 30 pin docking port.

1.2 Precautions (Important, Please Read)

UPDATING iPod FIRMWARE

For proper operation of the PXDP, your iPod must be updated with the most recent version of Firmware from Apple. This is done on your computer. To Update the software on the iPod go to http://www.apple.com/ipod/download/. Follow the directions on the website to complete the download. There is no charge for this update.


PREVENTING DAMAGE TO YOUR VEHICLE OR iPod.

The manufacturer recommends unplugging the iPod when not in use. To eliminate the risk of an electrical short, we recommend disconnecting the car battery in most vehicles, prior to installation except in the following situations:

 Vehicles equipped with on-board navigation should not have the car's battery disconnected. Doing so may cause loss of memory settings. These settings would then have to be reprogrammed by an authorized car dealer for a fee to be paid by the vehicle's owner. For these vehicles, we recommend extreme caution when handling exposed 12V power or ground wires/connectors. •Vehicles that incorporate a security-code protecting the radio. If the car's battery or the radio's power plugs are disconnected, the radio will not operate without re-entering the security-code. If you have access to the security-code, feel comfortable disconnecting the battery and the radio's power connectors. Otherwise, do not disconnect the battery and exercise extreme caution while handling exposed 12V power or ground wires/connectors.

PROPER MOUNTING LOCATION

Securely install the interface in a location free from; heat, humidity, moving parts or direct sunlight. Beware of hotair flow from your vehicle's climate control system. We recommend securing the interface to a suitable location, free of sharp metal edges, using; double sided tape, Velcro or wire ties.



1.3 Configuration and Harness Selection

This section will instruct you on how to properly identify and/ or confirm the proper interface dip-switch configuration and vehicle specific harness selection.

Use the guide located in the back of this manual on page 18 to locate your vehicle, inform you of the proper dip-switch configuration for the interface, and the vehicle specific harness that you will need for your particular vehicle. Depending on the type of PXDP kit you purchased, it might include a bundle of different vehicle harnesses or none at all. If the kit contains many harnesses, only one will be needed for your specific vehicle. If the kit came without any vehicle harness, your authorized iSimple® dealer will have the harness for you to purchase separately.

As you consult the application guide, please take a moment to review our IMPORTANT COMPATIBILITY NOTES listed with each of the vehicle manfactuers. These notes will inform you of any issues or circumstances that can affect the compatibility of our product with your factory audio system and accessories. Some situations result in the loss of use of some factory audio players. Please read and understand these notes before proceeding with the installation.

1.6 Programming the PXDP

Now that you have identified the correct harness and dipswitch configuration using the application guide, it is now time to program the interface. To program the interface, set the dip-switches located on the side of the interface (see Fig.1 below) to the congfiguration listed for your vehicle in the application guide. Switches are in their default setting of "off" in the up position and are turned "on" when switched down. This programs the PXDP to work with the vehicle in which it will be installed. The dip-switches MUST be set before the interface is plugged into the vehicle. Otherwise the PXDP will not work correctly.

1 2 3 4 5 6 7 8 DIP ON \$\frac{1}{2}\$

Fig.1 Side view of Interface with dip switches


Please Refer to Page 18 for Configuration Settings

PLEASE NOTE: If after installation you experience low volume from the interface, Dipswitch 6 can be turned on for a 6Db gain.

Chapter 2- General Installation

2.1 Installation Location

Most installations will require you to remove the factory radio in order to plug in the vehicle specific harness. Some vehicles may require you to connect the interface to a factory pre-run CD changer cable. The location of these CD changer cables will vary by vehicle. Some common locations of these cables are in the trunk, behind the glove box, and in or under a center console. (see Fig.2 below)



2.2 Pre-Installation Checklist

At this time and before beginning the installation please ensure that:

- You have read and understand the precautions outlined in section 1.2
- Your iPod's Firmware is up to date. (section 1.2)
- You have your radio's security code.(when applicable, see section 1.2)
- The dip-switches on the interface have been set with the proper configuration. (see section 1.3)
- You have in your possession the correct harness for your vehicle. (see sec. 1.3)
- You have determined your installation location. (see section 2.1)

If any of these steps has not been taken, STOP. Only when ALL of these steps have been taken should you proceed with the rest of the installation.

2.3 Wiring Connections

Some vehicle specific harnesses require wiring connections that involve splicing of wires. If you are not confident in making these connections to your radio's wiring harness, we recommend you seek professional installation. You can visit www.isimplesolutions.com and click on the dealer link at the top of the page to find an authorized professional installer.

Make these connections only after verifying the proper circuit on your radio harness with a voltmeter. With the key OFF and the negative test lead of the voltmeter firmly touching a bare metal chassis part of your car, begin probing the wires in the main radio harness with the positive test lead. The constant 12V+ circuit should read a continuous 12 volts or higher.

Once you've identified the constant 12V+ circuit, strip back about 1/8" of the insulation. Now take the positive test lead and insert it into the wire stranding so that you can now probe for a suitable ground location in the dash cavity using the negative test lead. Bare chassis metal is the recommended ground spot. The voltmeter will read a constant 12 volts or higher when you have found a good ground point. Attach the BLACK ground wire to this spot with either an existing bolt or screw or use a metal piercing screw. You also have the option of splicing into the ground wire in the main radio harness. Probe the remaining wires with the negative test lead until you again find a circuit that reads a constant 12 volts on the voltmeter. When you've found a circuit that reads constant 12 volts, turn the dash light dimmer control to make sure you have not probed the illumination dimmer circuit. If the circuit continues to read a constant 12 volts or higher regardless of the dimmer position, you have found the ground wire. If not, continue testing until you do. Some vehicles do not have a ground wire in their main radio harness and instead ground through their mounting brackets to the dash. In these cases, you will have to ground the black wire to the bare metal chassis inside the dash. Once the ground wire is connected, please finish your wiring connections by splicing in the external YELLOW wire from the vehicle specific harness.

Vehicle Specific Harnesses that require wiring connections:

PXHFD1 – connect the Yellow wire to constant 12V+ & connect the Black wire to ground.

PXHFD2 – connect the Yellow wire to constant 12V+ & connect the Black wire to ground.

PXHFD3 – connect the Yellow wire to constant 12V+ & connect the Black wire to ground.

PXHGM3 – connect the Yellow wire to constant 12V+ & connect the Black wire to ground.

PXHVW2 – connect both the Black and Black/White wires to ground.

2.4 Installation at the CD Changer Location

In this section you will learn how to install the PXDP in the factory CD changer location. If your vehicle is equipped with a factory CD changer you will need to disconnect it from the factory pre-run harness in order to connect the PXDP interface. If your vehicle is not equipped with a factory CD changer, you will need to locate the factory pre-run harness. This may involve the removal of the; center console, glove box, or carpeted side panels in the trunk. Please consult your vehicle's dealership or a local car audio professional for instruction or assistance with locating the factory CD changer connection if necessary.

- 1. Connect your vehicle specific Harness to the factory prerun CD changer harness in the vehicle.
- 2. Make any necessary wiring connections on your vehicle specific harness. Please see section 2.3 for details on making these wiring connections.
- 3. Now that the interface is connected to the radio, you will need to test the operation of the interface before permanently running the black iPod docking cable or reassembling the dash.

First, connect the black iPod cable to the iPod. The iPod should indicate that it is being charged. Turn on the factory radio and press the button that would activate the factory CD changer to select the iPod. It may take up to three minutes for the interface to initialize to the radio (this only happens the very first time you select the iPod). Once the iPod has been selected, press Play on the iPod. You should be able to hear the music on your iPod through your factory radio. Now press the "Next Track" button on the radio. The iPod should change to the next song on the iPod. By pressing the "Previous Track" button on the radio the iPod should change to the previous song. With the operation of the interface confirmed, you may continue with the installation. If you experience difficulties in operation, please see our troubleshooting chart in section 3.2.

- 4. Decide on a convenient location to mount your iPod.
- 5. Run the docking cable from the interface to the desired mounting location. Use caution to not cut, pinch, or crimp the cable during this step. Avoid moving parts, vehicle wiring harnesses and areas of excessive heat when routing the cable.
- 6. Secure the interface in the vehicle using; double sided tape, Velcro or wire ties. Make sure to check for proper clearance and avoid moving parts. Take into account the size of the interface and the wire harness and do not force the interface and harness into a space that is too tight, damage to the harness may result.
- 7. Now that the interface is secured and the docking cable has been run, you are ready to enjoy your iPod in your vehicle!

2.5 Installation at the Radio

In this section you will learn how to install the PXDP behind the radio. If your vehicle is equipped with a factory CD changer or other external audio source, you will need to disconnect it from the back of the radio in order to connect the PXDP interface.

- 1. Carefully remove the radio from the vehicle. If your radio uses a Security Code, make sure that you have the code before unplugging the radio. Some vehicles require the use of special tools to remove the radio. Please consult your vehicle's dealership or a local car audio professional for instruction or assistance with radio removal if necessary.
- 2. Make any necessary wiring connections on your vehicle specific harness. Please see section 2.3 for details on making these wiring connections.
- 3. Connect the Vehicle Specific Harness to the CD changer port on the back of the radio. Be sure to make a firm connection but do not force it. If there is difficulty making the connection, please consult the application guide to confirm your vehicle specific harness selection.

4. Now that the interface is connected to the radio, you will need to test the operation of the interface before permanently running the black iPod docking cable or reassembling the dash.

First, connect the black iPod cable to the iPod. The iPod should indicate that it is being charged. Turn on the factory radio and press the button that would activate the factory CD changer to select the iPod. It may take up to three minutes for the interface to initialize to the radio (this only happens the very first time you select the iPod). Once the iPod has been selected, press Play on the iPod. You should be able to hear the music on your iPod through your factory radio. Now press the "Next Track" button on the radio. The iPod should change to the next song on the iPod. By pressing the "Previous Track" button on the radio the iPod should change to the previous song. With the operation of the interface confirmed, you may continue with the installation. If you experience difficulties in operation, please see our troubleshooting chart in section 3.2.

- 5. Decide on a convenient location to mount your iPod.
- 6. Run the docking cable from the interface to the desired mounting location. Use caution to not cut, pinch, or crimp the cable during this step. Avoid moving parts, vehicle wiring harnesses and areas of excessive heat when routing the cable.
- 7. Secure the interface in the dash cavity behind the radio using; double sided tape, Velcro or wire ties. Make sure to check for proper clearance and avoid moving parts. Take into account the size of the interface and the wire harness and do not force the interface and harness into a space that is too tight, damage to the harness may result.
- 8. Now that the interface is secured and the docking cable has been run, you may reinstall the radio and replace any panels that may have been removed to access the radio. You are ready to enjoy your iPod in your vehicle!

Chapter 3- Operation

3.1 Operation

SELECTING THE IPOD

To select the iPod from the radio, press the button that would normally activate the factory CD changer. This button varies by vehicle manufacturers. In some applications the PXDP is accessed like an XM reciever, In these cases you will press the appropriate activation button. Some radio models require pressing the "Seek >" button once, after pressing the CD button. Yet, it may also be necessary to press Play on the iPod itself to begin playback. In some cases, if it is the first time selecting the iPod from the radio it may take up to three minutes for the PXDP to initialize.

CONTROLLING THE IPOD FROM THE RADIO

With the PXDP interface, the radio will control the iPod as if it were a factory CD changer. Therefore, operation will be done by using the same buttons you would use to control a factory CD changer. For more details on your particular radio, consult your vehicle's owner's manual.

The PXDP interface allows you to skip songs forward and backwards and also to fast forward and rewind through a particular song. In general, most radios will utilize "seek" or "track" buttons to control these functions.

CONTROLLING THE IPOD FROM THE IPOD

The PXDP interface allows you to keep full control of the iPod from the click wheel. You can browse files and change playlist on the iPod. You can also skip songs forward and backwards from the iPod. The PXDP interface does not disable any functionality of the iPod!

RADIO DISPLAY DURING IPOD OPERTION

Some factory radio's may show DISC and TRACK numbers on the display of the radio. The PXDP interface does not send any information from the iPod to the radio. This means that the DISC and TRACK numbers shown on the display will not and can not reflect the song number on the iPod due to the complex nature of the music library. Some factory radio's may flash zero's on the display of the radio, or toggle back and forth between 1:00 and 2:00. All these are normal behaviors and do not represent a malfunction.

CONTROLING THE IPOD FROM THE STEERING WHEEL CONTROLS

If your vehicle's steering wheel controls have the ability to select track and control the forward and rewind functions of your factory CD changer, then they will also control these same functions on the iPod.

3.2 Troubleshooting

Symptom	Cause	Remedy
No Power	Blown fuse in vehicle fuse block.	Replace fuse with same amp rating. If the fuse blows again, call tech support.
No Power	Bad connection	Check cable and wiring connection.
Alternator noise is heard (Changes with Engine RPM)	Improper wiring creates a ground loop.	Install a Ground loop isolator or seek professional service from a local car audio shop.
You can hear music from the iPod but you cant control it from the radio.	The Firmware on the iPod may not be updated.	Update the Firmware on the iPod. See section 1.2 of this manual.
Radio is not recognizing PXDP interface	Bad cables or cables are not connected properly between converter box and car radio.	Check connection and cables, push in firmly.
Radio is not recognizing PXDP interface	Wrong configuration on the interface.	Select the right pconfiguration for your car. (See section 1.3).
Radio is not recognizing PXDP interface	Yellow and black wires are not connected to Constant 12V+ and Ground. (When applicable)	Please read wiring instructions in chapter 2 of this manual and see if your car requires to connect the yellow and black cable to power and ground.
iPod Audio is Low or Distorted	PXDP interface is con- nected with an external CD changer or other external factory audio source.	Disconnect the factory external audio source.
iPod is not charging	Yellow and black wires are not connected to Constant 12V+ and Ground. (When applicable)	Please read your vehicles section in this manual and see if your car requires to connect the yellow and black cable to power and ground.

3.3 Warranty

One Year Limited Warranty

The quality controls used in the manufacture of this product This warranty covers any supplied or manufactured parts of this product that, upon inspection by iSimple authorized personnel, is found to have failed in normal use due to defects in material or workmanship. This warranty does not apply to installation expenses.

Attempting to service or modify this unit, operating this unit under conditions other than the recommended voltage will render this WARRANTY VOID.

Unless otherwise prescribed by law, iSimple shall not be liable for any personal injury, property damage and or any incidental or consequential damages of any kind (including water damage) resulting from malfunctions, defects, misuse, improper installation or alteration of this product.

All parts of this iSimple product are guaranteed for a period of 1 year as follows:

Within the first 12 months from date of purchase, subject to the conditions above, iSimple will repair or replace the product at their discretion, if it is defective in material or workmanship providing it is returned to an Authorized iSimple's Dealer, with PROOF OF PURCHASE from an authorized iSimple dealer.

3.4 Warning

This equipment may be reset by unintentional electrostatic discharge during operation. Exposure to direct sunlight or extreme heat may cause damage or malfunction.

3.5 FCC Class B Radio Frequency Interference Statement

This equipment has been tested and found to comply with the limits for a Class B digital device, pursuant to Part 15 of FCC rules. These limits are designed to provide reasonable protection against harmful interference in a residential installation. This equipment generates, uses, and can radiate radio frequency energy and, if not installed and used in accordance with the instructions, may cause harmful interference to radio communications. However, there is no guarantee that interference will not occur in a particular installation. If this equipment does cause harmful interference to radio or television reception, which can be determined by turning the equipment off and on, the user is encouraged to try to correct the interference by one or more of the following measures:

- 1. Reorientate or relocate the receiving antenna.
- 2. Increase the separation between the equipment and receiver.
- 3. Connect the equipment into an outlet on a circuit different from that of which the receiver is connected.
- 4. Consult the dealer or an experienced radio / television technical for help

Notice: The changes or modifications not expressly approved by the party responsible for compliance could void the user authority to operate the equipment.

			Dipswito	h Settings &	Harness Applicat	ions				
/lake	Model	Year	Part #	Harness	Dip Switch Settings**	Vehicle Specific Notes				
\cura	CL	1998-2000	PXDP	PXHHD1	1,4,8 ON					
	CL	1996-1997	PXDP	PXHCH2	1,4,8 ON					
	Integra	1998-2001	PXDP	PXHHD1	1,4,8 ON					
	Integra	1992-1997	PXDP	PXHCH2	1,4,8 ON					
	Legend	1992-1995	PXDP	PXHCH2	1,4,8 ON					
	RL	1998-2002	PXDP	PXHHD1	1,4,8 ON					
	RL	1996-1997	PXDP	PXHCH2	1,4,8 ON					
	RSX	2002	PXDP	PXHHD1	1,4,8 ON					
	TL	1999-2002	PXDP	PXHHD1	1,4,8 ON					
	TL	1996-1997	PXDP	PXHCH2	1,4,8 ON					
	Vigor	1992-1994	PXDP	PXHCH2	1,4,8 ON					
	All Models	2003-2007	Not Compatible							
	MDX	All Years	Not Compatible							
	SLX	All Years	Not Compatible							
	NSX	All Years	Not Compatible							
	IMPORTANT ACURA APPLICATION INFORMATION									
	PXDP: Not compatible with any far dash 6 disk cd changer. Not comp			changer, or Cassette player. The	se devices must be disconnected during t	he installation and will no longer function. Not compatible with factory radios that have an in				
4-1-	Madal				Bir O ind Continue	Wallah Control Mana				
	Model	Year	Part #	Harness	Dip Switch Settings*	Vehicle Specific Notes				
	All Models (Except Below)	Year 1998-2004	Part # PXDP	PXHAD1	1,8 ON	Vehicle Specific Notes Connect at pre-wired 13-pin cable in the left rear trunk.				
		Year	Part #	PXHAD1 PXHAD2 + PXHVW2*	1,8 ON 1,8 ON	Connect at pre-wired 13-pin cable in the left rear trunk.				
	All Models (Except Below) All Models (Except Below)	Year 1998-2004 1998-2004	Part # PXDP PXDP	PXHAD1 PXHAD2 + PXHVW2* IMPORTANT /	1,8 ON 1,8 ON Audi application informatio i	Connect at pre-wired 13-pin cable in the left rear trunk.				
	All Models (Except Below) All Models (Except Below) PXDP: Not compatible with any far	Year 1998-2004 1998-2004 ctory external audio source	Part # PXDP PXDP PXDP	PXHAD1 PXHAD2 + PXHVW2* IMPORTANT /	1,8 ON 1,8 ON Audi application informatio i	Connect at pre-wired 13-pin cable in the left rear trunk.				
udi	All Models (Except Below) All Models (Except Below)	Year 1998-2004 1998-2004 ctory external audio source	Part # PXDP PXDP PXDP	PXHAD1 PXHAD2 + PXHVW2* IMPORTANT /	1,8 ON 1,8 ON Audi application informatio i	Connect at pre-wired 13-pin cable in the left rear trunk.				
udi lake	All Models (Except Below) All Models (Except Below) PXDP: Not compatible with any faspecial adapter harness PXHAD2	Year 1998-2004 1998-2004 ctory external audio sources well as PXHVW2 and constraints.	Part # PXDP PXDP PXDP ce such as: XM tuner, CD connect at radio.	PXHAD1 PXHAD2 + PXHVW2* IMPORTANT A	1,8 ON 1,8 ON AUDI APPLICATION INFORMATION se devices must be disconnected during the control of	Connect at pre-wired 13-pin cable in the left rear trunk. N he installation and will no longer function. Vehicles with Symphony sound systems must use Vehicle Specific Notes				
udi ake	All Models (Except Below) All Models (Except Below) PXDP: Not compatible with any faspecial adapter harness PXHAD2 and Model	Year 1998-2004 1998-2004 ctory external audio source as well as PXHVW2 and co	Part # PXDP PXDP es such as: XM tuner, CD of connect at radio. Part #	PXHAD1 PXHAD2 + PXHVW2* IMPORTANT A changer, or Cassette player. The Harness	1,8 ON 1,8 ON AUDI APPLICATION INFORMATION se devices must be disconnected during to Dip Switch Settings* 3,4,8, ON	Connect at pre-wired 13-pin cable in the left rear trunk. N he installation and will no longer function. Vehicles with Symphony sound systems must use Vehicle Specific Notes Not Compatible with DSP radios, Trunk Mounting Location				
udi lake	All Models (Except Below) All Models (Except Below) PXDP: Not compatible with any fa special adapter harness PXHAD2 Model 3 Series	Year 1998-2004 1998-2004 ctory external audio sour as well as PXHVW2 and c Year 1996-2005	Part # PXDP PXDP ce such as: XM tuner, CD connect at radio. Part # ISBM72	PXHAD1 PXHAD2 + PXHVW2* IMPORTANT A changer, or Cassette player. The Harness Included	1,8 ON 1,8 ON AUDI APPLICATION INFORMATION se devices must be disconnected during the control of	Connect at pre-wired 13-pin cable in the left rear trunk. N he installation and will no longer function. Vehicles with Symphony sound systems must use Vehicle Specific Notes Not Compatible with DSP radios, Trunk Mounting Location Not Compatible with DSP radios, Trunk Mounting Location				
udi lake	All Models (Except Below) All Models (Except Below) PXDP: Not compatible with any faspecial adapter harness PXHAD2 of Model 3 Series 5 Series	Year 1998-2004 1998-2004 ctory external audio sourras well as PXHVW2 and c Year 1996-2005 1996-2005	Part # PXDP PXDP ce such as: XM tuner, CD connect at radio. Part # ISBM72 ISBM72	PXHAD1 PXHAD2 + PXHVW2* IMPORTANT A changer, or Cassette player. The Harness Included Included	1,8 ON 1,8 ON AUDI APPLICATION INFORMATION se devices must be disconnected during to Dip Switch Settings* 3,4,8, ON 3,4,8, ON	Connect at pre-wired 13-pin cable in the left rear trunk. N he installation and will no longer function. Vehicles with Symphony sound systems must use Vehicle Specific Notes Not Compatible with DSP radios, Trunk Mounting Location				
udi lake	All Models (Except Below) All Models (Except Below) PXDP: Not compatible with any faspecial adapter harness PXHAD2 Model 3 Series 5 Series 7 Series	Year 1998-2004 1998-2004 ctory external audio soura as well as PXHVW2 and c Year 1996-2005 1996-2005 1999-2001 2001-2006	Part # PXDP PXDP ce such as: XM tuner, CD connect at radio. Part # ISBM72 ISBM72 ISBM72	PXHAD1 PXHAD2 + PXHVW2* IMPORTANT A changer, or Cassette player. The Harness Included Included Included	1,8 ON 1,8 ON 1,8 ON AUDI APPLICATION INFORMATIOI se devices must be disconnected during to Dip Switch Settings* 3,4,8, ON 3,4,8, ON 3,4,8, ON 3,4,8, ON 3,4,8, ON	Connect at pre-wired 13-pin cable in the left rear trunk. N he installation and will no longer function. Vehicles with Symphony sound systems must use Vehicle Specific Notes Not Compatible with DSP radios, Trunk Mounting Location				
udi lake	All Models (Except Below) All Models (Except Below) PXDP: Not compatible with any faspecial adapter harness PXHAD2 of Model 3 Series 5 Series 7 Series Mini X5	Year 1998-2004 1998-2004 ctory external audio sourras well as PXHVW2 and c Year 1996-2005 1996-2005 1999-2001 2001-2006 1999-2005	Part # PXDP PXDP De such as: XM tuner, CD of connect at radio. Part # ISBM72 ISBM72 ISBM72 ISBM72 ISBM72 ISBM72 ISBM72	PXHAD1 PXHAD2 + PXHVW2* IMPORTANT A changer, or Cassette player. The Harness Included Included Included Included	1,8 ON 1,8 ON 1,8 ON AUDI APPLICATION INFORMATIOI se devices must be disconnected during to Dip Switch Settings* 3,4,8, ON 3,4,8, ON 3,4,8, ON 3,4,8, ON 3,4,8, ON 3,4,8, ON	Connect at pre-wired 13-pin cable in the left rear trunk. N he installation and will no longer function. Vehicles with Symphony sound systems must use Vehicle Specific Notes Not Compatible with DSP radios, Trunk Mounting Location				
udi lake	All Models (Except Below) All Models (Except Below) PXDP: Not compatible with any faspecial adapter harness PXHAD2 at Model 3 Series 5 Series 7 Series Mini X5 Z3/Z5	Year 1998-2004 1998-2004 ctory external audio soura as well as PXHVW2 and c Year 1996-2005 1996-2005 1999-2001 2001-2006 1999-2005 1998-2003	Part # PXDP PXDP Description of the part #	PXHAD1 PXHAD2 + PXHVW2* IMPORTANT of the changer, or Cassette player. The Harness Included Included Included Included Included Included	1,8 ON 1,8 ON 1,8 ON AUDI APPLICATION INFORMATIOI se devices must be disconnected during to Dip Switch Settings* 3,4,8, ON	Connect at pre-wired 13-pin cable in the left rear trunk. N he installation and will no longer function. Vehicles with Symphony sound systems must use Vehicle Specific Notes Not Compatible with DSP radios, Trunk Mounting Location				
udi lake	All Models (Except Below) All Models (Except Below) PXDP: Not compatible with any faspecial adapter harness PXHAD2 of Model 3 Series 5 Series 7 Series Mini X5	Year 1998-2004 1998-2004 ctory external audio sourras well as PXHVW2 and c Year 1996-2005 1996-2005 1999-2001 2001-2006 1999-2005	Part # PXDP PXDP De such as: XM tuner, CD of connect at radio. Part # ISBM72 ISBM72 ISBM72 ISBM72 ISBM72 ISBM72 ISBM72	PXHAD1 PXHAD2 + PXHVW2* IMPORTANT of the changer, or Cassette player. The changer, or Cassette player. The changer of the change	1,8 ON 1,8 ON 1,8 ON AUDI APPLICATION INFORMATIOI se devices must be disconnected during to Dip Switch Settings* 3,4,8, ON 3,4,8, ON 3,4,8, ON 3,4,8, ON 3,4,8, ON 3,4,8, ON	Connect at pre-wired 13-pin cable in the left rear trunk. N he installation and will no longer function. Vehicles with Symphony sound systems must use Vehicle Specific Notes Not Compatible with DSP radios, Trunk Mounting Location Not Compatible with DSP radios, Trunk Mounting Location				
Jake Audi Jake SMW	All Models (Except Below) All Models (Except Below) PXDP: Not compatible with any faspecial adapter harness PXHAD2 at Model 3 Series 5 Series 7 Series Mini X5 Z3/Z5 Z4	Year 1998-2004 1998-2004 ctory external audio sour as well as PXHVW2 and c Year 1996-2005 1996-2005 1999-2001 2001-2006 1999-2005 1998-2003 2003-2005	Part # PXDP PXDP Description of the part #	PXHAD1 PXHAD2 + PXHVW2* IMPORTANT of the shanger, or Cassette player. The harness Included	1,8 ON 1,8 ON 1,8 ON AUDI APPLICATION INFORMATIOI se devices must be disconnected during to Dip Switch Settings* 3,4,8, ON	Connect at pre-wired 13-pin cable in the left rear trunk. N he installation and will no longer function. Vehicles with Symphony sound systems must u Vehicle Specific Notes Not Compatible with DSP radios, Trunk Mounting Location				

Make	Model	Year	Part #	Harness	Dip Switch Settings*	Vehicle Specific Notes
Buick	Century	1997-2003	PXDP	PXHGM1 & GMH32T	3,8 ON	Must use GMH32T "T"-harness then plug *PXHGM1 behind radio.
	Le Sabre	1999-2002	PXDP	PXHGM3	1,3,8 ON	
	Park Ave	1995-2005	PXDP	PXHGM1 & GMH32T	3,8 ON	Must use GMH32T "T"-harness then plug *PXHGM1 behind radio.
	Rainier	2005	PXDP	PXHGM3	1,3,8 ON	
	Regal	1995-2003	PXDP	PXHGM1 & GMH32T	3,8 ON	Must use GMH32T "T"-harness then plug *PXHGM1 behind radio.
	Rendezvous	2003-2005	PXDP	PXHGM3	1,3,8 ON	
	Riviera	1996-1999	PXDP	PXHGM1 & GMH32T	3,8 ON	Must use GMH32T "T"-harness then plug *PXHGM1 behind radio.
	Roadmaster	1995-1996	PXDP	PXHGM1 & GMH32T	3,8 ON	Must use GMH32T "T"-harness then plug *PXHGM1 behind radio.
	Allure	2005	Not Compatible			
	LaCrosse	2005	Not Compatible			
				IMPORTANT B	UICK APPLICATION INFORMATION	DN
						the installation and will no longer function. GM vehicles 1998 – 2004 not equipped with a fact follow this link to the Tech Brief to retain XM:
					NOT compatible because they do not ha	
Make	Model	Year	Part #	Harness	Dip Switch Settings*	Vehicle Specific Notes
Cadillac	Catera	2001	PXDP	PXHGM2	3,8 ON	Behind radio or Trunk Mounting Location
	Deville	1995-2003	PXDP	PXHGM2	3,8 ON or 1,3,8 ON	Behind radio or Trunk Mounting Location
	El Dorado	1995-2002	PXDP	PXHGM2	3,8 ON	Trunk Mounting Location
	Escalade	1999-2002	PXDP	PXHGM1	3,8 ON	
	Escalade	2003-2006	PXDP	PXHGM3	1,3,8 ON or 2,3,8 ON	
	Escalade Seville	2003-2006 1995-2005	PXDP PXDP	PXHGM3 PXHGM2	1,3,8 ON or 2,3,8 ON 3,8 ON	
		========	17.51	PXHGM2	.,-,,-,-	TION
	Seville PXDP: Not compatible with	1995-2005	PXDP	PXHGM2 IMPORTANT CAE changer, or Cassette player. Thes	3,8 ON DILLAC APPLICATION INFORMA se devices must be disconnected during	the installation and will no longer function. GM vehicles 1998 - 2004 not equipped with a fact
	Seville PXDP: Not compatible with slave may not be able to su	1995-2005 n any factory external audio source pport an external device. Therefor	PXDP such as: XM tuner, CD ce the PXDP may not be co	PXHGM2 IMPORTANT CAE changer, or Cassette player. Thes ompatible. If you are an experience	3,8 ON DILLAC APPLICATION INFORMA se devices must be disconnected during	the installation and will no longer function. GM vehicles 1998 – 2004 not equipped with a fact follow this link to the Tech Brief to retain XM:
Make	Seville PXDP: Not compatible with slave may not be able to su	1995-2005 n any factory external audio source pport an external device. Therefor	PXDP such as: XM tuner, CD ce the PXDP may not be co	PXHGM2 IMPORTANT CAE changer, or Cassette player. Thes ompatible. If you are an experience	3,8 ON DILLAC APPLICATION INFORMA' se devices must be disconnected during ced installer, you can retain XM. Please	the installation and will no longer function. GM vehicles 1998 – 2004 not equipped with a fact follow this link to the Tech Brief to retain XM:
Make Chevrolet	Seville PXDP: Not compatible with slave may not be able to su http://peripheralelectronics	1995-2005 1 any factory external audio source pport an external device. Therefor .com/web/tech_dept.asp. 1995-19	PXDP such as: XM tuner, CD c e the PXDP may not be cc 99 Radios with built in CD	PXHGM2 IMPORTANT CAE changer, or Cassette player. Thes ompatible. If you are an experienc D player (Except Corvette) are N	3,8 ON DILLAC APPLICATION INFORMA' se devices must be disconnected during ced installer, you can retain XM. Please NOT compatible because they do not ha	the installation and will no longer function. GM vehicles 1998 – 2004 not equipped with a fact follow this link to the Tech Brief to retain XM: ve CD changer control functions.
	Seville PXDP: Not compatible with slave may not be able to su http://peripheralelectronics Model	1995-2005 n any factory external audio source poort an external device. Therefor c.com/web/tech_dept.asp. 1995-199 Year	PXDP such as: XM tuner, CD c e the PXDP may not be co 99 Radios with built in CD Part #	PXHGM2 IMPORTANT CAE changer, or Cassette player. Thes ompatible. If you are an experienc D player (Except Corvette) are N Harness	3,8 ON DILLAC APPLICATION INFORMA' se devices must be disconnected during ced installer, you can retain XM. Please NOT compatible because they do not ha Dip Switch Settings*	the installation and will no longer function. GM vehicles 1998 - 2004 not equipped with a fac follow this link to the Tech Brief to retain XM: ve CD changer control functions.
	Seville PXDP: Not compatible with slave may not be able to su http://peripheralelectronics Model Astro Van	1995-2005 n any factory external audio source poort an external device. Therefor c.com/web/tech_dept.asp. 1995-199 Year 1996-2005	PXDP such as: XM tuner, CD o e the PXDP may not be ct 99 Radios with built in CD Part # PXDP	PXHGM2 IMPORTANT CAE changer, or Cassette player. Thes ompatible. If you are an experienc D player (Except Corvette) are N Harness PXHGM1	3,8 ON DILLAC APPLICATION INFORMA' se devices must be disconnected during ced installer, you can retain XM. Please NOT compatible because they do not ha Dip Switch Settings* 3,8 ON	the installation and will no longer function. GM vehicles 1998 - 2004 not equipped with a fac e follow this link to the Tech Brief to retain XM: ve CD changer control functions.
	Seville PXDP: Not compatible with slave may not be able to su http://peripheralelectronics Model Astro Van Avalanche	n any factory external audio source poport an external device. Therefor c.com/web/tech_dept.asp. 1995-19: Year 1996-2005 2002	PXDP such as: XM tuner, CD of the PXDP may not be or 199 Radios with built in CB Part # PXDP PXDP	PXHGM2 IMPORTANT CAE changer, or Cassette player. Thes ompatible. If you are an experienc D player (Except Corvette) are N Harness PXHGM1 PXHGM1	3,8 ON DILLAC APPLICATION INFORMA'se devices must be disconnected during the devices must be deviced installer, you can retain XM. Please NOT compatible because they do not have been supported by the disconnected during the devices of the d	the installation and will no longer function. GM vehicles 1998 - 2004 not equipped with a fac follow this link to the Tech Brief to retain XM: ve CD changer control functions.
	Seville PXDP: Not compatible with slave may not be able to su http://peripheralelectronics Model Astro Van Avalanche Avalanche	n any factory external audio source poport an external device. Therefor com/web/tech_dept.asp. 1995-19: Year 1996-2005 2002 2003-2006	PXDP such as: XM tuner, CD of the PXDP may not be or 199 Radios with built in CB Part # PXDP PXDP PXDP PXDP	PXHGM2 IMPORTANT CAE changer, or Cassette player. Thes ompatible. If you are an experienc D player (Except Corvette) are N Harness PXHGM1 PXHGM1 PXHGM3	3,8 ON DILLAC APPLICATION INFORMA's devices must be disconnected during the di	the installation and will no longer function. GM vehicles 1998 - 2004 not equipped with a fac e follow this link to the Tech Brief to retain XM: ve CD changer control functions.
	Seville PXDP: Not compatible with slave may not be able to su http://peripheralelectronics Model Astro Van Avalanche Avalanche Blazer	n any factory external audio source poport an external device. Therefor com/web/tech_dept.asp. 1995-19: Year 1996-2005 2002 2003-2006 1998-2002	PXDP such as: XM tuner, CD of the PXDP may not be of the PXDP may n	PXHGM2 IMPORTANT CAE changer, or Cassette player. Thes ompatible. If you are an experienc D player (Except Corvette) are N Harness PXHGM1 PXHGM1 PXHGM3 PXHGM1	3,8 ON DILLAC APPLICATION INFORMA's devices must be disconnected during the di	the installation and will no longer function. GM vehicles 1998 - 2004 not equipped with a fac e follow this link to the Tech Brief to retain XM: ve CD changer control functions.
	Seville PXDP: Not compatible with slave may not be able to su http://peripheralelectronics Model Astro Van Avalanche Avalanche Blazer Camaro	1995-2005 n any factory external audio source poport an external device. Therefor c.com/web/tech_dept.asp. 1995-199 Year 1996-2005 2002 2003-2006 1998-2002 1997-2002	PXDP such as: XM tuner, CD of the PXDP may not be or 199 Radios with built in CB Part # PXDP PXDP PXDP PXDP PXDP PXDP PXDP PXDP PXDP	PXHGM2 IMPORTANT CAE changer, or Cassette player. Thes ompatible. If you are an experienc D player (Except Corvette) are N Harness PXHGM1 PXHGM1 PXHGM3 PXHGM1 PXHGM1 PXHGM1 PXHGM1 PXHGM1 PXHGM1	3,8 ON DILLAC APPLICATION INFORMA's devices must be disconnected during the di	the installation and will no longer function. GM vehicles 1998 - 2004 not equipped with a fac e follow this link to the Tech Brief to retain XM: ve CD changer control functions.
	Seville PXDP: Not compatible with slave may not be able to su http://peripheralelectronics Model Astro Van Avalanche Avalanche Blazer Camaro Cavalier	1995-2005 n any factory external audio source poport an external device. Therefor c.com/web/tech_dept.asp. 1995-199 Year 1996-2005 2002 2003-2006 1998-2002 1997-2002 1996-1999	PXDP such as: XM tuner, CD of the PXDP may not be or 199 Radios with built in CE Part # PXDP	PXHGM2 IMPORTANT CAL changer, or Cassette player. Thes ompatible. If you are an experience D player (Except Corvette) are N Harness PXHGM1 PXHGM1 PXHGM3 PXHGM1 PXHGM1 PXHGM1 PXHGM1 PXHGM1 PXHGM1 PXHGM1 PXHGM1	3,8 ON DILLAC APPLICATION INFORMA's devices must be disconnected during the disconnected during the distaller, you can retain XM. Please NOT compatible because they do not have been supported by the distaller of the distaller o	the installation and will no longer function. GM vehicles 1998 - 2004 not equipped with a fac e follow this link to the Tech Brief to retain XM: ve CD changer control functions.
	Seville PXDP: Not compatible with slave may not be able to su http://peripheralelectronics Model Astro Van Avalanche Avalanche Blazer Camaro Cavalier Cavalier	1995-2005 n any factory external audio source poport an external device. Therefor c.com/web/tech_dept.asp. 1995-199 Year 1996-2005 2002 2003-2006 1998-2002 1997-2002 1996-1999 2003-2005	PXDP such as: XM tuner, CD of the PXDP may not be or 199 Radios with built in CE Part # PXDP	PXHGM2 IMPORTANT CAL changer, or Cassette player. Thes ompatible. If you are an experience D player (Except Corvette) are N Harness PXHGM1 PXHGM1 PXHGM3 PXHGM1 PXHGM3	3,8 ON DILLAC APPLICATION INFORMA's devices must be disconnected during the disconnected during the distaller, you can retain XM. Please NOT compatible because they do not have been supported by the distaller of the distaller o	the installation and will no longer function. GM vehicles 1998 - 2004 not equipped with a fac e follow this link to the Tech Brief to retain XM: ve CD changer control functions.
	Seville PXDP: Not compatible with slave may not be able to su http://peripheralelectronics Model Astro Van Avalanche Avalanche Blazer Camaro Cavalier Colorado	1995-2005 n any factory external audio source poport an external device. Therefore.com/web/tech_dept.asp. 1995-199 Year 1996-2005 2002 2003-2006 1998-2002 1997-2002 1996-1999 2003-2005 2005	PXDP such as: XM tuner, CD of the PXDP may not be or any	PXHGM2 IMPORTANT CAL changer, or Cassette player. Thes ompatible. If you are an experient D player (Except Corvette) are N Harness PXHGM1 PXHGM1 PXHGM3 PXHGM1 PXHGM1 PXHGM1 PXHGM1 PXHGM1 PXHGM1 PXHGM3 PXHGM3 PXHGM3 PXHGM3 PXHGM3	3,8 ON DILLAC APPLICATION INFORMA's devices must be disconnected during the disconnected during the distaller, you can retain XM. Please NOT compatible because they do not have been supported by the distaller of the distaller o	the installation and will no longer function. GM vehicles 1998 - 2004 not equipped with a fac follow this link to the Tech Brief to retain XM: ve CD changer control functions. Vehicle Specific Notes
	Seville PXDP: Not compatible with slave may not be able to su http://peripheralelectronics Model Astro Van Avalanche Avalanche Blazer Camaro Cavalier Cavalier Colorado Corvette	1995-2005 n any factory external audio source poport an external device. Therefore.com/web/tech_dept.asp. 1995-199 Year 1996-2005 2002 2003-2006 1998-2002 1997-2002 1996-1999 2003-2005 2005 1997-2004	PXDP such as: XM tuner, CD of the PXDP may not be or 199 Radios with built in CE Part # PXDP	PXHGM2 IMPORTANT CAL changer, or Cassette player. Thes ompatible. If you are an experience D player (Except Corvette) are N Harness PXHGM1 PXHGM1 PXHGM3 PXHGM1 PXHGM1 PXHGM1 PXHGM1 PXHGM1 PXHGM1 PXHGM3 PXHGM3 PXHGM3 PXHGM3 PXHGM3 PXHGM3 PXHGM3	3,8 ON DILLAC APPLICATION INFORMA's devices must be disconnected during the disconnected during the distaller, you can retain XM. Please NOT compatible because they do not have been supported by the distaller of the distaller o	the installation and will no longer function. GM vehicles 1998 - 2004 not equipped with a fact follow this link to the Tech Brief to retain XM: ve CD changer control functions. Vehicle Specific Notes Trunk Mounting Location
	Seville PXDP: Not compatible with slave may not be able to su http://peripheralelectronics Model Astro Van Avalanche Avalanche Blazer Camaro Cavalier Colorado Corvette Corvette	1995-2005 n any factory external audio source poport an external device. Therefore.com/web/tech_dept.asp. 1995-199 Year 1996-2005 2002 2003-2006 1998-2002 1997-2002 1996-1999 2003-2005 2005 1997-2004 1997-2004	PXDP such as: XM tuner, CD of the PXDP may not be or any	PXHGM2 IMPORTANT CAL changer, or Cassette player. Thes ompatible. If you are an experience D player (Except Corvette) are N Harness PXHGM1 PXHGM1 PXHGM3 PXHGM1 PXHGM1 PXHGM1 PXHGM1 PXHGM1 PXHGM1 PXHGM3 PXHGM3 PXHGM3 PXHGM3 PXHGM3 PXHGM3 PXHGM3 PXHGM4	3,8 ON DILLAC APPLICATION INFORMA's devices must be disconnected during the disconnected during the distaller, you can retain XM. Please NOT compatible because they do not have been supported by the distaller of the distaller o	the installation and will no longer function. GM vehicles 1998 - 2004 not equipped with a fact follow this link to the Tech Brief to retain XM: ve CD changer control functions. Vehicle Specific Notes Trunk Mounting Location
	Seville PXDP: Not compatible with slave may not be able to su http://peripheralelectronics Model Astro Van Avalanche Avalanche Blazer Camaro Cavalier Colorado Corvette Corvette Impala	1995-2005 n any factory external audio source poport an external device. Therefore.com/web/tech_dept.asp. 1995-199 Year 1996-2005 2002 2003-2006 1998-2002 1997-2002 1996-1999 2003-2005 2005 1997-2004 1997-2004 1995-1999	PXDP such as: XM tuner, CD of the PXDP may not be or any	PXHGM2 IMPORTANT CAL changer, or Cassette player. Thes ompatible. If you are an experient D player (Except Corvette) are N Harness PXHGM1 PXHGM1 PXHGM3 PXHGM1 PXHGM1 PXHGM1 PXHGM1 PXHGM1 PXHGM3 PXHGM1 PXHGM3 PXHGM4 PXHGM8 PXHGM9 PXHGM1	3,8 ON DILLAC APPLICATION INFORMA's devices must be disconnected during the disconnected during the distaller, you can retain XM. Please NOT compatible because they do not hat the Dip Switch Settings* 3,8 ON 3,8 ON 3,8 ON 3,8 ON 3,8 ON 3,8 ON 1,3,8 ON 1,3,8 ON 1,3,8 ON 3,8 ON	the installation and will no longer function. GM vehicles 1998 - 2004 not equipped with a fact follow this link to the Tech Brief to retain XM: ve CD changer control functions. Vehicle Specific Notes Trunk Mounting Location
	Seville PXDP: Not compatible with slave may not be able to su http://peripheralelectronics Model Astro Van Avalanche Avalanche Blazer Camaro Cavalier Colorado Corvette Corvette Impala Impala	1995-2005 n any factory external audio source poport an external device. Therefore.com/web/tech_dept.asp. 1995-199 Year 1996-2005 2002 2003-2006 1998-2002 1997-2002 1996-1999 2003-2005 2005 1997-2004 1997-2004 1995-1999 2000-2005	PXDP such as: XM tuner, CD of the PXDP may not be or any	PXHGM2 IMPORTANT CAL changer, or Cassette player. Thes ompatible. If you are an experience D player (Except Corvette) are N Harness PXHGM1 PXHGM1 PXHGM3 PXHGM1 PXHGM1 PXHGM1 PXHGM1 PXHGM3 PXHGM3 PXHGM3 PXHGM4 PXHGM4 PXHGM4 PXHGM1 PXHGM4 PXHGM1 PXHGM1 PXHGM3 PXHGM3 PXHGM3 PXHGM3 PXHGM4 PXHGM1 PXHGM1 PXHGM1	3,8 ON DILLAC APPLICATION INFORMA's devices must be disconnected during the disconnected during the distaller, you can retain XM. Please NOT compatible because they do not have been supported by the distaller of the distaller o	the installation and will no longer function. GM vehicles 1998 - 2004 not equipped with a face follow this link to the Tech Brief to retain XM: ve CD changer control functions. Vehicle Specific Notes Trunk Mounting Location

Make	Model	Year	Part #	Harness	Dip Switch Settings*	Vehicle Specific Notes					
Chevrolet	Monte Carlo	2000-2005	PXDP	PXHGM3	3,8 ON						
	Silverado	1996-2002	PXDP	PXHGM1	3,8 ON						
	Silverado	2003-2006	PXDP	PXHGM3	1,3,8 ON						
	Suburban	1995-2002	PXDP	PXHGM1	3,8 ON						
	Suburban	2003-2006	PXDP	PXHGM3	1,3,8 ON						
	Tahoe	1995-2002	PXDP	PXHGM1	3,8 ON						
	Tahoe	2003-2006	PXDP	PXHGM3	1,3,8 ON						
	Trailblazer	2002-2007	PXDP	PXHGM3	1,3,8 ON or 2,3,8 ON						
	Venture	1997-1999	PXDP	PXHGM1	3,8 ON						
	Venture	2004-2005	PXDP	PXHGM3	1,3,8 ON or 2,3,8 ON						
				IMPORTANT CH	IEVROLET APPLICATION INFO	RMATION					
						uring the installation and will no longer function. GM vehicles 1998 - 2004 not equipped with a factory					
						Please follow this link to the Tech Brief to retain XM:					
	1 1	2 2 2 2		. , .		ot have CD changer control functions.					
Make	Model	Year	Part #	Harness	Dip Switch Settings*	Vehicle Specific Notes					
Chrysler	All Models	2002-2005	PXDP	PXHCH3	· · · · · · · · · · · · · · · · · · ·	Must be non-CANBUS, if radio is an REF,REC,RAQ, RAK series, vehicles are not compatible					
	All Models	19992001	PXDP	PXHCH2	4,8 ON	*1999 Radios with rounded corners use PXHCH2					
	All Models	1995-1999*	PXDP	PXHCH1	1,4,8 ON	*1999 Radios with square corners use PXHCH1					
	Pacifica	2006	PXDP	PXHCH3	4,8 ON						
	Sebring	2006	PXDP	PXHCH3	4,8 ON						
	IMPORTANT CHRYSLER APPLICATION INFORMATION										
						uring the installation and will no longer function. To determine if your 2002-2005 vehicle is compatible,					
						ries is indicated on the front of the radio. 1999 Chrysler vehicles have one of two different style radios.					
	These two radios use difference part# PXHCH2.	rent harnesses. The shape of the ra	dio face will determine w	hich harness you will use. If	your radio face is SQUARE, you will u	use the harness part# PXHCH1. If your radio face is OVAL (rounded corners), you will use the harness					
M-I	•	V	D #	Hamasa	Die Codesk Cassians	Webble Constitution					
Make	Model All Models	Year 2002-2005	Part #	Harness PXHCH3	Dip Switch Settings* 4.8 ON	Vehicle Specific Notes Must be non-CANBUS, if radio is an REF.REC.RAQ, RAK series, vehicles are not compatible					
Dodge	7 III 1110 a 010	2002 2000	.,	. ,	11						
	All Models	1999*-2001	PXDP	PXHCH2	4,8 ON	*1999 Radios with rounded corners use PXHCH2					
	All Models	1995-1999*	PXDP	PXHCH1	1,4,8 ON	*1999 Radios with square corners use PXHCH1					
	IMPORTANT DODGE APPLICATION INFORMATION										
						uring the installation and will no longer function. To determine if your 2002-2005 vehicle is compatible,					
						ries is indicated on the front of the radio. 1999 Chrysler vehicles have one of two different style radios. Ise the harness part# PXHCH1. If your radio face is OVAL (rounded corners), you will use the harness					
	part# PXHCH2.	rent narnesses. The snape of the ra	idio tace Will decermine W	nich narness you will use. It	your radio face is SQUAKE , you will u	ise the namess part# PARCH1. If your radio face is OVAL trounded corners, you will use the namess					
Make	Model	Vaca	Don't #	Ианнала	Din Cuital Cattings	Vahiala Cassifia Natas					
		Year 1995-1998	Part #	Harness PXHCH1	Dip Switch Settings* 1.4.8 ON	Vehicle Specific Notes All models must have "Disc ^ " printed on Preset Button # 1.					
	All Madala			PAHUH I	1,4,0 UN	All models must have bisc printed on Preset Button # 1.					
Eagle	All Models	INPORTANT EAGLE APPLICATION INFORMATION									
	PXDP: Not compatible wit		such as: XM tuner, CD c	hanger, or Cassette player. T	hese devices must be disconnected d	NATION uring the installation and will no longer function. If your vehicle is equipped with a factory CD changer					

lake	Model	Year	Part #	Harness	Dip Switch Settings*	Vehicle Specific Notes				
rd	Crown Victoria	1998-2003	PXDP	PXHFD3	2,8 ON					
	Crown Victoria	1995-1997	PXDP	PXHFD2	2,8 ON					
	Crown Victoria	1995-1997	PXDP	PXHFD1	2,8 ON	*If equipped with JBL, use PXHFD1 at Rear Control Unit in trunk				
	Escape	2001-2004	PXDP	PXHFD3	2,8 ON					
	Econoline	1998-2004	PXDP	PXHFD3	2.8 ON					
	Econoline	1997	PXDP	PXHFD2	2.8 ON					
	Escort	1997-2004	PXDP	PXHFD2	2.8 ON					
	Excursion	2000-2004	PXDP	PXHFD3	2.8 ON					
	Expedition	1999-2002	PXDP	PXHFD3	2.8 ON					
	Expedition	1997-1998	PXDP	PXHFD2	2.8 ON					
	Explorer	1998-2004	PXDP	PXHFD3	2.8 ON					
	Explorer	1995-1997	PXDP	PXHFD2	2,8 ON					
	Explorer	1995-1997	PXDP	PXHFD1	2,8 ON	*If equipped with JBL, use PXHFD1 at Rear Control Unit in trunk				
	Freestar	2004	PXDP	PXHFD3	2,8 ON	in equipped man edg, dee 174 in 21 de 116din eeiner en en en en en en				
	F-series Pick Up	1998-2003	PXDP	PXHFD3	2,8 ON					
	F-series Pick Up	1995-1997	PXDP	PXHFD2	2,8 ON					
	Focus	2000-2003	PXDP	PXHFD4	2.8 ON	Not compatible with factory installed Blaupunkt radio				
	Mustang	2001-2003	PXDP	PXHFD3	2.8 ON	1100 companie wich factory installed bladpunkt fadio				
	Ranger	1998-2004	PXDP	PXHFD3	2.8 ON					
	Ranger	1995-1997	PXDP	PXHFD2	2,8 ON					
	Sport Trac	2000-2004	PXDP	PXHFD3	2,8 ON					
	Taurus	1996-2005	PXDP	PXHFD1	2.8 ON	Trunk Mounting Location				
	Thunderbird	2000-2004	PXDP	PXHFD3	2,8 ON	Trunk Mounting Location				
	Windstar		PXDP	PXHFD3	2,8 ON					
	Miliastal.	1999-2004	PAUP		·	TION				
	IMPORTANT FORD APPLICATION INFORMATION PVDB. Not comparible with any factory extended quite course cuch act VM tunes. CD changes on Cascette player. These devices must be disconnected during the installation and will be legan function. Not comparible with factory gadies with built in S.									
	PXDP: Not compatible with any factory external audio source such as: XM tuner, CD changer, or Cassette player. These devices must be disconnected during the installation and will no longer function. Not compatible with factory radios with built CD changers. Compatible with factory navigation radios.									
ake	Model	Year	Part #	Harness	Dip Switch Settings*	Vehicle Specific Notes				
IC	Canyon	2004-2006	PXDP	PXHGM3	1,3,8 ON or 2,3,8 ON	PXHGMTCD harness is required to retain factory CD Changer (if equipped)				
	Envoy	1999-2001	PXDP	PXHGM1	3,8 ON	····				
	Envoy	2002-2007	PXDP	PXHGM3	1,3,8 ON or 2,3,8 ON					
	Denali	1995-2002	PXDP	PXHGM1	3.8 ON					
	Denali	2003-2006	PXDP	PXHGM3	1.3.8 ON					
	Doridii		PXDP	PXHGM1	3.8 ON					
	. limmy	1998-2002								
	Jimmy	1998-2002			3 8 UN					
	Sonoma	1998-2002	PXDP	PXHGM1	3,8 ON					
	Sonoma Safari	1998-2002 1996-2005	PXDP PXDP	PXHGM1 PXHGM1	3,8 ON					
	Sonoma Safari Savana	1998-2002 1996-2005 1999-2000	PXDP PXDP PXDP	PXHGM1 PXHGM1 PXHGM1	3,8 ON 3,8 ON					
	Sonoma Safari Savana Sierra	1998-2002 1996-2005 1999-2000 1995-2002	PXDP PXDP PXDP PXDP	PXHGM1 PXHGM1 PXHGM1 PXHGM1	3,8 ON 3,8 ON 3,8 ON					
	Sonoma Safari Savana Sierra Sierra	1998-2002 1996-2005 1999-2000 1995-2002 2003-2006	PXDP PXDP PXDP PXDP PXDP	PXHGM1 PXHGM1 PXHGM1 PXHGM1 PXHGM3	3,8 ON 3,8 ON 3,8 ON 1,3,8 ON					
	Sonoma Safari Savana Sierra Sierra Suburban	1998-2002 1996-2005 1999-2000 1995-2002 2003-2006 1995-2002	PXDP PXDP PXDP PXDP PXDP PXDP PXDP	PXHGM1 PXHGM1 PXHGM1 PXHGM1 PXHGM3 PXHGM1	3,8 ON 3,8 ON 3,8 ON 1,3,8 ON 3,8 ON					
	Sonoma Safari Savana Sierra Sierra Suburban Suburban	1998-2002 1996-2005 1999-2000 1995-2002 2003-2006 1995-2002 2003-2006	PXDP PXDP PXDP PXDP PXDP PXDP PXDP PXDP	PXHGM1 PXHGM1 PXHGM1 PXHGM1 PXHGM3 PXHGM1 PXHGM1 PXHGM3	3,8 ON 3,8 ON 3,8 ON 1,3,8 ON 3,8 ON 1,3,8 ON					
	Sonoma Safari Savana Sierra Sierra Suburban Suburban Yukon/XL	1998-2002 1996-2005 1999-2000 1995-2002 2003-2006 1995-2002 2003-2006 1995-2002	PXDP PXDP PXDP PXDP PXDP PXDP PXDP PXDP	PXHGM1 PXHGM1 PXHGM1 PXHGM3 PXHGM3 PXHGM1 PXHGM3 PXHGM3 PXHGM3 PXHGM1	3,8 ON 3,8 ON 3,8 ON 1,3,8 ON 3,8 ON 1,3,8 ON 3,8 ON					
	Sonoma Safari Savana Sierra Sierra Suburban Suburban	1998-2002 1996-2005 1999-2000 1995-2002 2003-2006 1995-2002 2003-2006	PXDP PXDP PXDP PXDP PXDP PXDP PXDP PXDP	PXHGM1 PXHGM1 PXHGM1 PXHGM1 PXHGM3 PXHGM1 PXHGM3 PXHGM1 PXHGM3 PXHGM1 PXHGM1	3,8 ON 3,8 ON 3,8 ON 1,3,8 ON 3,8 ON 1,3,8 ON					

Honda Accord 1998-2002 PXDP PXHHD1 1,4,8 DN Civic 1998-2004 PXDP PXHHD1 1,4,8 DN Civic 1998-2004 PXDP PXHHD1 1,4,8 DN Civic 1998-2004 PXDP PXHHD1 1,4,8 DN CRV 1998-2004 PXDP PXHHD1 1,4,8 DN CRV 1998-2004 PXDP PXHHD1 1,4,8 DN Del Sol 1993-1997 PXDP PXHCH2 1,4,8 DN Del Sol 1993-1997 PXDP PXHCH2 1,4,8 DN Del Sol 1993-1997 PXDP PXHCH2 1,4,8 DN Del Sol 1993-1997 PXDP PXHHD1 1,4,8 DN Del Sol 1993-1997 PXDP PXHHD1 1,4,8 DN Odyssey 1995-1997 PXDP PXHHD1 1,4,8 DN Odyssey 1995-1997 PXDP PXHHD1 1,4,8 DN Prelude 1998-2002 PXDP PXHHD1 1,2,4 B DN Prelude 1998-2001 PXDP PXHHD1 1,2,4 B DN Prelude 1998-2001 PXDP PXHHD1 1,4,8 DN Prelude 1998-1997 PXDP PXHD1 1,4,8 DN PRELUGE 1,4,8 DN PRELUGE 1,4,8 DN PXDP PXHD1 1,4,8 DN PXDP PX	
Civic 1998-2004 PXDP PXH-D1 1,4,8 DN	
Civic 1992-1997 PXDP PXHCH2 1,4,8 ON	
CRV	
CRV	
Del Sol 1993-1997 PXDP PXHCH2 1,4,8 DN	
Element 2002 PXDP PXHHD1 1,4,8 ON Insight 2001-2004 PXDP PXHHD1 1,4,8 ON Odyssey 1995-1997 PXDP PXHCH2 1,4,8 ON Odyssey 1998-2004 PXDP PXHHD1 1,4,8 ON Passport 1998-2002 PXDP PXHHD1 1,2,4,8 ON Prelude 1998-2001 PXDP PXHHD1 1,2,4,8 ON Prelude 1998-2001 PXDP PXHHD1 1,4,8 ON Prelude 1992-1997 PXDP PXHHD1 1,4,8 ON Prelude 1992-1997 PXDP PXHCH2 1,4,8 ON S2000 2000-2003 PXDP PXHHD1 1,4,8 ON All Models 2005-2007 Not Compatible Accord 2003-2004 Not Compatible Pilot All Years Not Compatible Ridgeline All Years Not Compatible S2000 2004 Not Compatible S2000 20	
Insight	
Odyssey	
Odyssey	
Passport 1998-2002 PXDP PXHHD1 1,2,4,8 ON Prelude 1998-2001 PXDP PXHHD1 1,4,8 ON Prelude 1992-1997 PXDP PXHCH2 1,4,8 ON S2000 2000-2003 PXDP PXHHD1 1,4,8 ON All Models 2005-2007 Not Compatible Accord 2003-2004 Not Compatible Pilot All Years Not Compatible Ridgeline All Years Not Compatible S2000 2004 Not Compatible PYDP Not compatible with any factory external audio source such as: XM tuner, CD changer, or Cassette player. These devices must be disconnected during the installation and will no longer function. Not compatible with factory radios (dash 6 disk cd changer. Not compatible with navigation radios. Make Model Year Part Harness Dip Switch Settings* Vehicle Specific Notes Hummer H2 2003-2006 PXDP PXHGM3 1,3,8 ON or 2,3,8 ON *2003-2005 Must disable factory XM Tuner if equipped	
Prelude 1998-2001 PXDP PXHPD1 1,4,8 ON Prelude 1992-1997 PXDP PXHPD1 1,4,8 ON S2000 2000-2003 PXDP PXHPD1 1,4,8 ON All Models 2005-2007 Not Compatible Accord 2003-2004 Not Compatible Pilot All Years Not Compatible Ridgeline All Years Not Compatible S2000 2004 Not Compatible DXDP: Not compatible with any factory external audio source such as: XM tuner, CD changer, or Cassette player. These devices must be disconnected during the installation and will no longer function. Not compatible with factory radios in dash 6 disk cd changer. Not compatible with navigation radios. Make Model Year Part Harness Dip Switch Settings* Vehicle Specific Notes Hummer H2 2003-2006 PXDP PXHGM3 1,3,8 ON or 2,3,8 ON *2003-2005 Must disable factory XM Tuner if equipped	
Prelude 1992-1997 PXDP PXHCH2 1,4,8 ON \$2000 2000-2003 PXDP PXHHD1 1,4,8 ON All Models 2005-2007 Not Compatible Accord 2003-2004 Not Compatible Pilot All Years Not Compatible Ridgeline All Years Not Compatible \$2000 2004 Not Compatible S2000 2004 Not Compatible **The Models Section Sec	
S2000 2000-2003 PXDP PXHHD1 1,4,8 ON All Models 2005-2007 Not Compatible Accord 2003-2004 Not Compatible Pilot All Years Not Compatible Ridgeline All Years Not Compatible S2000 2004 Not Compatible S2000 2004 Not Compatible IMPORTANT HONDA APPLICATION INFORMATION PXDP: Not compatible with any factory external audio source such as: XM tuner, CD changer, or Cassette player. These devices must be disconnected during the installation and will no longer function. Not compatible with factory radios dash 6 disk cd changer. Not compatible with navigation radios. Make Model Year Part # Harness Dip Switch Settings* Vehicle Specific Notes Hummer H2 2003-2006 PXDP PXHGM3 1,3,8 ON or 2,3,8 ON *2003-2005 Must disable factory XM Tuner if equipped	
All Models 2003-2004 Not Compatible Accord 2003-2004 Not Compatible Pilot All Years Not Compatible Ridgeline All Years Not Compatible S2000 2004 Not Compatible IMPORTANT HONDA APPLICATION INFORMATION PXDP: Not compatible with any factory external audio source such as: XM tuner, CD changer, or Cassette player. These devices must be disconnected during the installation and will no longer function. Not compatible with factory radios than 6 disk cd changer. Not compatible with navigation radios. Make Model Year Part # Harness Dip Switch Settings* Vehicle Specific Notes Hummer H2 2003-2006 PXDP PXHGM3 1,3,8 ON or 2,3,8 ON *2003-2005 Must disable factory XM Tuner if equipped	
Accord 2003-2004 Not Compatible Pilot All Years Not Compatible Ridgeline All Years Not Compatible S2000 2004 Not Compatible IMPORTANT HONDA APPLICATION INFORMATION PXDP: Not compatible with any factory external audio source such as: XM tuner, CD changer, or Cassette player. These devices must be disconnected during the installation and will no longer function. Not compatible with factory radios to dash 6 disk cd changer. Not compatible with navigation radios. Make Model Year Part # Harness Dip Switch Settings* Vehicle Specific Notes Hummer H2 2003-2006 PXDP PXHGM3 1,3,8 ON or 2,3,8 ON *2003-2005 Must disable factory XM Tuner if equipped	
Pilot All Years Not Compatible Ridgeline All Years Not Compatible S2000 2004 Not Compatible IMPORTANT HONDA APPLICATION INFORMATION PXDP: Not compatible with any factory external audio source such as: XM tuner, CD changer, or Cassette player. These devices must be disconnected during the installation and will no longer function. Not compatible with factory radios to dash 6 disk cd changer. Not compatible with navigation radios. Make Model Year Part # Harness Dip Switch Settings* Vehicle Specific Notes Hummer H2 2003-2006 PXDP PXHGM3 1,3,8 ON or 2,3,8 ON *2003-2005 Must disable factory XM Tuner if equipped	
Ridgeline All Years Not Compatible S2000 2004 Not Compatible IMPORTANT HONDA APPLICATION INFORMATION PXDP: Not compatible with any factory external audio source such as: XM tuner, CD changer, or Cassette player. These devices must be disconnected during the installation and will no longer function. Not compatible with factory radios to dash 6 disk cd changer. Not compatible with navigation radios. Make Model Year Part # Harness Dip Switch Settings* Vehicle Specific Notes Hummer H2 2003-2006 PXDP PXHGM3 1,3,8 ON or 2,3,8 ON *2003-2005 Must disable factory XM Tuner if equipped	
S2000 2004 Not Compatible IMPORTANT HONDA APPLICATION INFORMATION PXDP: Not compatible with any factory external audio source such as: XM tuner, CD changer, or Cassette player. These devices must be disconnected during the installation and will no longer function. Not compatible with factory radios to dash 6 disk cd changer. Not compatible with navigation radios. Make Model Year Part # Harness Dip Switch Settings* Vehicle Specific Notes Hummer H2 2003-2006 PXDP PXHGM3 1,3,8 0N or 2,3,8 0N *2003-2005 Must disable factory XM Tuner if equipped	
IMPORTANT HONDA APPLICATION INFORMATION PXDP: Not compatible with any factory external audio source such as: XM tuner, CD changer, or Cassette player. These devices must be disconnected during the installation and will no longer function. Not compatible with factory radios dash 6 disk cd changer. Not compatible with navigation radios. Make Model Year Part # Harness Dip Switch Settings* Vehicle Specific Notes Hummer H2 2003-2006 PXDP PXHGM3 1,3,8 ON or 2,3,8 ON *2003-2005 Must disable factory XM Tuner if equipped	
PXDP: Not compatible with any factory external audio source such as: XM tuner, CD changer, or Cassette player. These devices must be disconnected during the installation and will no longer function. Not compatible with factory radios dash 6 disk cd changer. Not compatible with navigation radios. Make Model Year Part # Harness Dip Switch Settings* Vehicle Specific Notes Hummer H2 2003-2006 PXDP PXHGM3 1,3,8 ON or 2,3,8 ON *2003-2005 Must disable factory XM Tuner if equipped	
dash 6 disk cd changer. Not compatible with navigation radios.MakeModelYearPart #HarnessDip Switch Settings*Vehicle Specific NotesHummerH22003-2006PXDPPXHGM31,3,8 ON or 2,3,8 ON*2003-2005 Must disable factory XM Tuner if equipped	
Hummer H2 2003-2006 PXDP PXHGM3 1,3,8 ON or 2,3,8 ON *2003-2005 Must disable factory XM Tuner if equipped	hat have an in
, , , , , , , , , , , , , , , , , , , ,	
H3 2005 PXDP PXHGM3 1,3,8 ON or 2,3,8 ON	
IMPORTANT HUMMER APPLICATION INFORMATION	
PXDP: Not compatible with any factory external audio source such as: XM tuner, CD changer, or Cassette player. These devices must be disconnected during the installation and will no longer function.	
Make Model Year Part # Harness Dip Switch Settings* Vehicle Specific Notes	
Isuzu Amigo 1998-2002 PXDP PXHTY3 1,2,4,8 ON	
Rodeo 1998-2002 PXDP PXHTY3 1,2,4,8 ON	
Trooper 1998-2002 PXDP PXHTY3 1,2,4,8 ON	
IMPORTANT ISUZU APPLICATION INFORMATION	
PXDP: Not compatible with any factory external audio source such as: XM tuner, CD changer, or Cassette player. These devices must be disconnected during the installation and will no longer function.	
Make Model Year Part # Harness Dip Switch Settings* Vehicle Specific Notes	
Jaguar S-Type 2000-2002 PXDP PXHFD4 2,8 0N	
IMPORTANT JAGUAR APPLICATION INFORMATION	
PXDP: Not compatible with any factory external audio source such as: XM tuner, CD changer, or Cassette player. These devices must be disconnected during the installation and will no longer function.	

ake	Model	Year	Part #	Harness	Dip Switch Settings*	Vehicle Specific Notes				
ep	All Models	2002-2005	PXDP	PXHCH3	4,8 ON	Must be non-CANBUS, if radio is an REF,REC,RAQ, RAK series, vehicles are not compatible				
	All Models	1999*-2001	PXDP	PXHCH2	4,8 ON	*1999 Radios with rounded corners use PXHCH2				
	All Models	1995-1999*	PXDP	PXHCH1	1,4,8 ON	*1999 Radios with square corners use PXHCH1				
	IMPORTANT JEEP APPLICATION INFORMATION									
	PXDP: Not compatible with any factory external audio source such as: XM tuner, CD changer, or Cassette player. These devices must be disconnected during the installation and will no longer function. To determine if your 2002-2005 vehicle is compati									
						s is indicated on the front of the radio. 1999 Chrysler vehicles have one of two different style r				
		nt harnesses. The shape of the r	adio face will determine w	iich harness you will use. If y	our radio face is SQUARE, you will use	the harness part# PXHCH1. If your radio face is OVAL (rounded corners), you will use the ha				
	part# PXHCH2.					V 44 1 0 W 10				
(e	Model	Year	Part #	Harness	Dip Switch Settings*	Vehicle Specific Notes				
oln	Aviator	2002-2003	PXDP	PXHFD3	2,8 ON					
	Continental	1998-2004	PXDP	PXHFD3	2,8 ON					
	Continental	1995-1997	PXDP	PXHFD2	2,8 ON					
	Continental*	1995-1997	PXDP	PXHFD1	2,8 ON	*If equipped with JBL, use PXHFD1 at Rear Control Unit in trunk				
	LS	2000-2003	PXDP	PXHFD3	2,8 ON					
	Mark VIII	1995-1998	PXDP	PXHFD2	2,8 ON					
	Navigator	1999-2003	PXDP	PXHFD3	2,8 ON					
	Navigator	1997-1998	PXDP	PXHFD2	2,8 ON					
	Town Car	1998-2003	PXDP	PXHFD3	2,8 ON					
	Town Car	1995-1997	PXDP	PXHFD2	2,8 ON					
	Town Car*	1995-1997	PXDP	PXHFD1	2,8 ON	*If equipped with JBL, use PXHFD1 at Rear Control Unit in trunk				
	IMPORTANT LINCOLN APPLICATION INFORMATION									
	PXDP: Not compatible with any factory external audio source such as: XM tuner, CD changer, or Cassette player. These devices must be disconnected during the installation and will no longer function. Not compatible with factory radios with built-in 6-									
	CD changers. Compatible wit	h factory navigation radios.								
ke	Model	Year	Part #	Harness	Dip Switch Settings*	Vehicle Specific Notes				
zda	B-series Truck	1998-2001	PXDP	PXHFD3	2,8 ON					
	B-series Truck	1997	PXDP	PXHFD2	2,8 ON					
					MAZDA APPLICATION INFORMA					
	PXDP: Not compatible with a	any factory external audio source	such as: XM tuner, CD cl	anger, or Cassette player. Th	nese devices must be disconnected duri	ng the installation and will no longer function.				
(e	Model	Year	Part #	Harness	Dip Switch Settings*	Vehicle Specific Notes				
cury	Cougar				1.2.8 ON					
ou.y		1999-2004	PXDP	PXHFD4	1,2,0 014	·				
ou. y	Grand Marquis	1999-2004 1998-2003	PXDP PXDP	PXHFD4 PXHFD3	2,8 ON					
ou. y	Grand Marquis Grand Marquis									
ou. y		1998-2003	PXDP	PXHFD3	2,8 ON	*If equipped with JBL, use PXHFD1 at Rear Control Unit in trunk				
 ,	Grand Marquis	1998-2003 1995-1997	PXDP PXDP	PXHFD3 PXHFD2	2,8 ON 2,8 ON	*If equipped with JBL, use PXHFD1 at Rear Control Unit in trunk				
u.,	Grand Marquis Grand Marquis	1998-2003 1995-1997 1995-1997	PXDP PXDP PXDP	PXHFD3 PXHFD2 PXHFD1	2,8 ON 2,8 ON 2,8 ON	*If equipped with JBL, use PXHFD1 at Rear Control Unit in trunk				
 ,	Grand Marquis Grand Marquis Mountaineer	1998-2003 1995-1997 1995-1997 1998-2004	PXDP PXDP PXDP PXDP	PXHFD3 PXHFD2 PXHFD1 PXHFD3	2,8 ON 2,8 ON 2,8 ON 2,8 ON 2,8 ON	*If equipped with JBL, use PXHFD1 at Rear Control Unit in trunk *If equipped with JBL, use PXHFD1 at Rear Control Unit in trunk				
 ,	Grand Marquis Grand Marquis Mountaineer Mountaineer	1998-2003 1995-1997 1995-1997 1998-2004 1995-1997	PXDP PXDP PXDP PXDP PXDP	PXHFD3 PXHFD2 PXHFD1 PXHFD3 PXHFD2	2,8 ON 2,8 ON 2,8 ON 2,8 ON 2,8 ON 2,8 ON	*If equipped with JBL, use PXHFD1 at Rear Control Unit in trunk				
 ,	Grand Marquis Grand Marquis Mountaineer Mountaineer Mountaineer Sable	1998-2003 1995-1997 1995-1997 1998-2004 1995-1997 1995-1997 1996-2005	PXDP PXDP PXDP PXDP PXDP PXDP PXDP PXDP	PXHFD3 PXHFD2 PXHFD1 PXHFD3 PXHFD2 PXHFD1 PXHFD1 PXHFD1	2,8 ON 2,8 ON 2,8 ON 2,8 ON 2,8 ON 2,8 ON 2,8 ON	*If equipped with JBL, use PXHFD1 at Rear Control Unit in trunk *If equipped with JBL, use PXHFD1 at Rear Control Unit in trunk				
 ,	Grand Marquis Grand Marquis Mountaineer Mountaineer Mountaineer Sable Tracer	1998-2003 1995-1997 1995-1997 1998-2004 1995-1997 1995-1997 1996-2005 1995-2004	PXDP PXDP PXDP PXDP PXDP PXDP PXDP PXDP	PXHFD3 PXHFD1 PXHFD1 PXHFD3 PXHFD2 PXHFD1 PXHFD1 PXHFD1 PXHFD1	2,8 ON 2,8 ON 2,8 ON 2,8 ON 2,8 ON 2,8 ON 2,8 ON 2,8 ON 2,8 ON	*If equipped with JBL, use PXHFD1 at Rear Control Unit in trunk				
Jul. ,	Grand Marquis Grand Marquis Mountaineer Mountaineer Mountaineer Sable	1998-2003 1995-1997 1995-1997 1998-2004 1995-1997 1995-1997 1996-2005	PXDP PXDP PXDP PXDP PXDP PXDP PXDP PXDP	PXHFD3 PXHFD2 PXHFD1 PXHFD3 PXHFD2 PXHFD1 PXHFD1 PXHFD1 PXHFD1 PXHFD1 PXHFD3	2,8 ON 2,8 ON 2,8 ON 2,8 ON 2,8 ON 2,8 ON 2,8 ON 2,8 ON 2,8 ON 2,8 ON	*If equipped with JBL, use PXHFD1 at Rear Control Unit in trunk *If equipped with JBL, use PXHFD1 at Rear Control Unit in trunk *If equipped with JBL, use PXHFD1 at Rear Control Unit in trunk				
,	Grand Marquis Grand Marquis Mountaineer Mountaineer Mountaineer Sable Tracer Villager	1998-2003 1995-1997 1995-1997 1998-2004 1995-1997 1995-1997 1996-2005 1995-2004 1999-2002	PXDP PXDP PXDP PXDP PXDP PXDP PXDP PXDP	PXHFD3 PXHFD2 PXHFD1 PXHFD3 PXHFD2 PXHFD1 PXHFD1 PXHFD1 PXHFD1 PXHFD3 IMPORTANT M	2,8 ON 2,8 ON 2,8 ON 2,8 ON 2,8 ON 2,8 ON 2,8 ON 2,8 ON 2,8 ON 2,8 ON	*If equipped with JBL, use PXHFD1 at Rear Control Unit in trunk *If equipped with JBL, use PXHFD1 at Rear Control Unit in trunk *If equipped with JBL, use PXHFD1 at Rear Control Unit in trunk				
	Grand Marquis Grand Marquis Mountaineer Mountaineer Mountaineer Sable Tracer Villager	1998-2003 1995-1997 1995-1997 1998-2004 1995-1997 1995-1997 1996-2005 1995-2004 1999-2002	PXDP PXDP PXDP PXDP PXDP PXDP PXDP PXDP	PXHFD3 PXHFD2 PXHFD1 PXHFD3 PXHFD2 PXHFD1 PXHFD1 PXHFD1 PXHFD1 PXHFD3 IMPORTANT M	2,8 ON 2,8 ON 2,8 ON 2,8 ON 2,8 ON 2,8 ON 2,8 ON 2,8 ON 2,8 ON 2,8 ON	*If equipped with JBL, use PXHFD1 at Rear Control Unit in trunk *If equipped with JBL, use PXHFD1 at Rear Control Unit in trunk *If equipped with JBL, use PXHFD1 at Rear Control Unit in trunk				
·	Grand Marquis Grand Marquis Mountaineer Mountaineer Mountaineer Sable Tracer Villager PXDP: Not compatible with a CD changers. Compatible with	1998-2003 1995-1997 1995-1997 1998-2004 1995-1997 1996-2005 1995-2004 1999-2002	PXDP PXDP PXDP PXDP PXDP PXDP PXDP PXDP	PXHFD3 PXHFD2 PXHFD1 PXHFD3 PXHFD2 PXHFD1 PXHFD1 PXHFD1 PXHFD1 PXHFD3 IMPORTANT M	2,8 ON	*If equipped with JBL, use PXHFD1 at Rear Control Unit in trunk *If equipped with JBL, use PXHFD1 at Rear Control Unit in trunk *If equipped with JBL, use PXHFD1 at Rear Control Unit in trunk IATION In the installation and will no longer function. Not compatible with factory radios with built-in least control unit in trunk				
ke	Grand Marquis Grand Marquis Mountaineer Mountaineer Mountaineer Sable Tracer Villager PXDP: Not compatible with a CD changers. Compatible with	1998-2003 1995-1997 1995-1997 1998-2004 1995-1997 1995-1997 1996-2005 1995-2004 1999-2002	PXDP PXDP PXDP PXDP PXDP PXDP PXDP PXDP	PXHFD3 PXHFD2 PXHFD1 PXHFD3 PXHFD2 PXHFD1 PXHFD1 PXHFD1 PXHFD1 PXHFD3 IMPORTANT M manger, or Cassette player. Th	2,8 ON Dip Switch Settings*	*If equipped with JBL, use PXHFD1 at Rear Control Unit in trunk *If equipped with JBL, use PXHFD1 at Rear Control Unit in trunk *If equipped with JBL, use PXHFD1 at Rear Control Unit in trunk				
·	Grand Marquis Grand Marquis Mountaineer Mountaineer Mountaineer Sable Tracer Villager PXDP: Not compatible with a CD changers. Compatible with	1998-2003 1995-1997 1995-1997 1998-2004 1995-1997 1996-2005 1995-2004 1999-2002	PXDP PXDP PXDP PXDP PXDP PXDP PXDP PXDP	PXHFD3 PXHFD1 PXHFD3 PXHFD3 PXHFD1 PXHFD1 PXHFD1 PXHFD1 PXHFD3 IMPORTANT M tanger, or Cassette player. Th	2,8 ON	*If equipped with JBL, use PXHFD1 at Rear Control Unit in trunk *If equipped with JBL, use PXHFD1 at Rear Control Unit in trunk *If equipped with JBL, use PXHFD1 at Rear Control Unit in trunk IATION Ing the installation and will no longer function. Not compatible with factory radios with built-in (Vehicle Specific Notes				
ke	Grand Marquis Grand Marquis Mountaineer Mountaineer Mountaineer Sable Tracer Villager PXDP: Not compatible with a CD changers. Compatible with Model Quest	1998-2003 1995-1997 1995-1997 1998-2004 1995-1997 1995-1997 1996-2005 1995-2004 1999-2002 any factory external audio source ch factory navigation radios.	PXOP PXOP PXOP PXOP PXOP PXOP PXOP PXOP	PXHFD3 PXHFD1 PXHFD3 PXHFD3 PXHFD2 PXHFD1 PXHFD1 PXHFD1 PXHFD3 IMPORTANT M tanger, or Cassette player. Th	2,8 ON ERCURY APPLICATION INFORM Dip Switch Settings* 2,8 ON VISSAN APPLICATION INFORMA	*If equipped with JBL, use PXHFD1 at Rear Control Unit in trunk *If equipped with JBL, use PXHFD1 at Rear Control Unit in trunk *If equipped with JBL, use PXHFD1 at Rear Control Unit in trunk IATION Ing the installation and will no longer function. Not compatible with factory radios with built-in (Vehicle Specific Notes				

Make	Model	Year	Part #	Harness	Dip Switch Settings*	Vehicle Specific Notes					
Oldsmobile	Achieva	1996-1998	PXDP	PXHGM3	1,3,8 ON	Trunk/CD Changer Mounting Location					
	Alero	2003-2004	PXDP	PXHGM3	2,3,8 ON						
	Alero	1999-2000	PXDP	PXHGM2	3,8 ON	Trunk Mounting Location					
	Aurora	2001-2004	PXDP	PXHGM2	3,8 ON	Trunk Mounting Location					
	Aurora	1995-1999	PXDP	PXHGM2	3,8 ON	Trunk Mounting Location					
	Bravada	2004	PXDP	PXHGM3	1,3,8 ON or 2,3,8 ON						
	Bravada	1997-2001	PXDP	PXHGM1	3,8 ON						
	Cutlass	1997-1999	PXDP	PXHGM2	3,8 ON	Trunk Mounting Location					
	Cutlass Supreme	1995-1997	PXDP	PXHGM2	3,8 ON	Trunk Mounting Location					
	Eighty-Eight	1996-1999	PXDP	PXHGM2	3,8 ON	Trunk Mounting Location					
	Intrigue	1998-2001	PXDP	PXHGM2	3,8 ON	Trunk Mounting Location					
	LSS	1996-1999	PXDP	PXHGM2	3,8 ON	Trunk Mounting Location					
	Regency	1997-1998	PXDP	PXHGM2	3,8 ON	Trunk Mounting Location					
	Silhouette	2004	PXDP	PXHGM3	2,3,8 ON						
	Silhouette	1996-1999	PXDP	PXHGM2	3,8 ON	Trunk Mounting Location					
				IMPORTANT OL	DSMOBILE APPLICATION INFORM	ATION					
	PXDP: Not compatible with any factory external audio source such as: XM tuner, CD changer, or Cassette player. These devices must be disconnected during the installation and will no longer function. GM vehicles 1998 - 2004 not equipped with a fact										
	slave may not be able to support an external device. Therefore the PXDP may not be compatible. If you are an experienced installer, you can retain XM. Please follow this link to the Tech Brief to retain XM:										
		om/web/tech_dept.asp. 1995-1	999 Radios with built in CD p	layer (Except Corvette) ar	e NOT compatible because they do not hav	•					
Make	Model	Year	Part #	Harness	Dip Switch Settings*	Vehicle Specific Notes					
Plymouth	All Models	1995-2000	PXDP	PXHCH1	1,4,8 ON	All models must have "Disc ^ " printed on Preset Button # 1.					
	Neon	2002-2004	PXDP	PXHGM3	1,4,8 ON						
	IMPORTANT PLYMOUTH APPLICATION INFORMATION PXDP: Not compatible with any factory external audio source such as: XM tuner, CD changer, or Cassette player. These devices must be disconnected during the installation and will no longer function.										
		· ·		• • • • • • • • • • • • • • • • • • • •		•					
Make	Model	Year	Part #	Harness	Dip Switch Settings*	Vehicle Specific Notes					
Pontiac	Aztec	2003-2005	PXDP	PXHGM3	1,3,8 ON or 2,3,8 ON						
	Bonneville	2000-2005	PXDP	PXHGM2	3,8 ON	Trunk Mounting Location					
	Bonneville	1996-1999	PXDP	PXHGM1	3,8 ON						
	Firebird / Trans Am	1996-2002	PXDP	PXHGM1	3,8 ON						
	Grand AM	2003-2005	PXDP	PXHGM3	1,3,8 ON or 2,3,8 ON						
	Grand AM	1996-2000	PXDP	PXHGM1	3,8 ON						
	Montana	2004-2005	PXDP	PXHGM3	1,3,8 ON or 2,3,8 ON						
	Montana	1999-2000	PXDP	PXHGM1	3,8 ON						
	Sunfire	2003-2005	PXDP	PXHGM3	1,3,8 ON						
	Sunfire	1996-1999	PXDP	PXHGM1	3,8 ON						
	TransSport	1996-1998	PXDP	PXHGM1	3,8 ON						
	Vibe	2004-2005	PXDP	PXHGM3	1,3,8 ON or 2,3,8 ON						
	G6	2005	Not Compatible								
	Grand Prix	2004-2007	Not Compatible								
				IMPORTANT F	PONTIAC APPLICATION INFORMAT	ION					
						the installation and will no longer function. GM vehicles 1998 – 2004 not equipped with a factory follow this link to the Tech Brief to retain XM:					
					e NOT compatible because they do not have						
	7 "1			,	, , , , , , , , , , , , , , , , , , , ,	•					

Make	Model	Year	Part #	Harness	Dip Switch Settings*	Vehicle Specific Notes				
Saturn	All Models	1995-1999	PXDP	PXHGM1	3,8 ON					
		IMPORTANT SATURN APPLICATION INFORMATION PXDP: Not compatible with any factory external audio source such as: XM tuner, CD changer, or Cassette player. These devices must be disconnected during the installation and will no longer function.								
Make	Model	Year	Part #	Harness	Dip Switch Settings*	Vehicle Specific Notes				
Scion	tC	2003-2007	PXDP	PXHTY3	1,2,4,8 ON	When using the PXHTY3 the green wires must be cut on the PXHTY3 harness				
	хA	2003-2005	PXDP	PXHTY3	1,2,4,8 ON	When using the PXHTY3 the green wires must be cut on the PXHTY3 harness				
	хВ	2003-2005	PXDP	PXHTY3	1,2,4,8 ON	When using the PXHTY3 the green wires must be cut on the PXHTY3 harness				
					ION APPLICATION INFORM					
		· ·				uring the installation and will no longer function.				
Make	Model	Year	Part #	Harness	Dip Switch Settings*	Vehicle Specific Notes				
Toyota	4Runner	1998-2005	PXDP	PXHTY3	1,2,4,8 ON	When using the PXHTY3 the green wires must be cut on the PXHTY3 harness				
	4Runner	2006-2007	PXDP	PXHTY3 or PXH2TY1	1,2,4,8 ON	When using the PXHTY3 the green wires must be cut on the PXHTY3 harness				
	Avalon	1998-2005	PXDP	PXHTY3	1,2,4,8 ON	When using the PXHTY3 the green wires must be cut on the PXHTY3 harness				
	Avalon	2006-2007	PXDP	PXHTY3 or PXH2TY1	1,2,4,8 ON	When using the PXHTY3 the green wires must be cut on the PXHTY3 harness				
	Camry	1998-2005	PXDP	PXHTY3	1,2,4,8 ON	When using the PXHTY3 the green wires must be cut on the PXHTY3 harness				
	Camry	2006-2007	PXDP	PXHTY3 or PXH2TY1	1,2,4,8 ON	When using the PXHTY3 the green wires must be cut on the PXHTY3 harness				
	Celica	1998-2005	PXDP	PXHTY3	1,2,4,8 ON	When using the PXHTY3 the green wires must be cut on the PXHTY3 harness				
	Corolla	1998-2005	PXDP	PXHTY3	1,2,4,8 ON	When using the PXHTY3 the green wires must be cut on the PXHTY3 harness				
	Corolla	2006-2007	PXDP	PXHTY3 or PXH2TY1	1,2,4,8 ON	When using the PXHTY3 the green wires must be cut on the PXHTY3 harness				
	Echo	2000-2005	PXDP	PXHTY3	1,2,4,8 ON	When using the PXHTY3 the green wires must be cut on the PXHTY3 harness				
	Highlander	2001-2004	PXDP	PXHTY3	1,2,4,8 ON	When using the PXHTY3 the green wires must be cut on the PXHTY3 harness				
	Highlander	2006-2007	PXDP	PXHTY3 or PXH2TY1	1,2,4,8 ON	When using the PXHTY3 the green wires must be cut on the PXHTY3 harness				
	Land Cruiser	1998-2005	PXDP	PXHTY3	1,2,4,8 ON	When using the PXHTY3 the green wires must be cut on the PXHTY3 harness				
	Land Cruiser	2006-2007	PXDP	PXHTY3 or PXH2TY1	1,2,4,8 ON	When using the PXHTY3 the green wires must be cut on the PXHTY3 harness				
	Matrix	2003-2004	PXDP	PXHGM3	1,3,8 ON					
	Matrix	2005-2007	PXDP	PXHTY3 or PXH2TY1	1,2,4,8 ON	When using the PXHTY3 the green wires must be cut on the PXHTY3 harness				
	MR2	2000-2005	PXDP	PXHTY3	1,2,4,8 ON	When using the PXHTY3 the green wires must be cut on the PXHTY3 harness				
	RAV4	1998-2005	PXDP	PXHTY3	1,2,4,8 ON	When using the PXHTY3 the green wires must be cut on the PXHTY3 harness				
	Sequoia	2001-2005	PXDP	PXHTY3	1,2,4,8 ON	When using the PXHTY3 the green wires must be cut on the PXHTY3 harness				
	Sequoia	2006-2007	PXDP	PXHTY3 or PXH2TY1	1,2,4,8 ON	When using the PXHTY3 the green wires must be cut on the PXHTY3 harness				
	Sienna	1998-2005	PXDP	PXHTY3	1,2,4,8 ON	When using the PXHTY3 the green wires must be cut on the PXHTY3 harness				

Make	Model	Year	Part #	Harness	Dip Switch Settings*	Vehicle Specific Notes						
Toyota	Sienna	2006-2007	PXDP	PXHTY3 or PXH2TY1	1,2,4,8 ON	When using the PXHTY3 the green wires must be cut on the PXHTY3 harness						
	Solara	1999-2005	PXDP	PXHTY3	1,2,4,8 ON	When using the PXHTY3 the green wires must be cut on the PXHTY3 harness						
	Solara	2006-2007	PXDP	PXHTY3 or PXH2TY1	1,2,4,8 ON	When using the PXHTY3 the green wires must be cut on the PXHTY3 harness						
	Supra	1998	PXDP	PXHTY3	1,2,4,8 ON	When using the PXHTY3 the green wires must be cut on the PXHTY3 harness						
	T100	1998	PXDP	PXHTY3	1,2,4,8 ON	When using the PXHTY3 the green wires must be cut on the PXHTY3 harness						
	Tacoma	1998-2005	PXDP	PXHTY3	1,2,4,8 ON	When using the PXHTY3 the green wires must be cut on the PXHTY3 harness						
	Tacoma	2006-2007	PXDP	PXHTY3 or PXH2TY1	1,2,4,8 ON	When using the PXHTY3 the green wires must be cut on the PXHTY3 harness						
	Tercel	1998	PXDP	PXHTY3	1,2,4,8 ON	When using the PXHTY3 the green wires must be cut on the PXHTY3 harness						
	Tundra	2000-2007	PXDP	PXHTY3	1,2,4,8 ON	When using the PXHTY3 the green wires must be cut on the PXHTY3 harness						
	Prius	All Years	Not Compatible									
	Highlander	2008	Not Compatible									
	5	IMPORTANT TOYOTA APPLICATION INFORMATION										
		PXDP: Not compatible with any factory external audio source such as: XM tuner, CD changer, or Cassette player. These devices must be disconnected during the installation and will no longer function. When using the PXHTY3 with 2006-2007 vehicles the										
	green wires must be cut on the PXHTY3 harness. Fully compatible with factory installed Toyota Navigation Systems. Not compatible with Hybrid vehicles.											
Make	Model	Year	Part #	Harness	Dip Switch Settings*	Vehicle Specific Notes						
Volkswagen	All Models	1998-2006	PXDP	PXHVW1	1,8 ON	Trunk Mounting Location						
	All Models	1998-2006	PXDP	PXHVW2	1,8 ON	For use with Single DIN radios						
	All Models	2003-2006	PXDP	PXHVW3	1,8 ON	For use with Double DIN radios						
	IMPORTANT VOLKSWAGEN APPLICATION INFORMATION											
	PXDP: Not compatible wi	th any factory external audio sourc	e such as: XM tuner, CD c	hanger, or Cassette player. The	se devices must be disconnected du	ring the installation and will no longer function. Not compatible with vehicles equipped with a factory						
				ness and install the PXDP behin	d the radio. This will avoid the pos	sibility of inherent noise problems with the factory VW CD changer cable that is found in some vehicles.						
	Double DIN (4" Tall) VW	radios require the PXHVW3 to con	nect behind the radio.									
	PXHVW3: When using th	e PXHVW3 harness, connect the lo	ose black lead to suitable (chassis ground. If equipped with	factory satellite, remove the blue (DEM sub harness from the main OEM harness to plug in the PXHVW3 harness.						

Notes



iSimple Solutions®, a division of AAMP of America™ 13160 56th Court Clearwater, Florida 33760 Ph. 866-788-4237 support@isimplesolutions.com ©2009 AAMP of Florida, Inc.



For Best Performance Have It Professionally Installed.





USIMOIC® SoundByte®

FACTORY RADIO
INTEGRATION FOR YOUR IPOD

MAKE THE CONNECTION



iPod





FIND YOUR VEHICLE



	LeSabre	1999-2002	HUMMER	H2	2003-2006
	Rainier	2005		H2T	2004-2006
	Rendezvous	2003-2005		H3	2005
(DeVille	1995-2000		Achieva	1996-1998
	El Dorado	1995-2002	\mathcal{A}	Alero	1999-2004
Patition	Escalade	1999-2006		Aurora	1995-2004
	SeVille	1995-2005		Bravada	1997-2001
The state of the s				Bravada	2004
	Astro Van	1996-2005		Cutlass	1997-1999
	Avalanche	2002-2006		Cutlass Supreme	1995-1997
	Blazer	1998-2002		Eighty-Eight	1996-1999
	Camaro	1997-2002		Intrique	1998-2001
	Cavalier	1996-2005		LSS	1996-1999
	Colorado	2004-2008		Regency	1997-1998
	Corvette	1997-2004		Silhouette	1996-1999
	Impala	1995-2005		Silhouette	2004
	Lumina	1996-1999			2001
	Malibu	1997-2000	M	Aztec	2003-2005
	Monte Carlo	1995-2005	V	Bonneville	1996-2005
	Silverado	1996-2006	V	Firebird	1996-2002
	Surburban	1995-2006		Grand Am	1996-2000
	Tahoe	1995-2006		Grand Am	2003-2005
	Trailblazer	2004-2006		Montana	1999-2000
	Venture	1997-2005		Montana	2004-2005
The state of the s				Sunfire	2003-2005
	Canyon	2004-2008		Sunfire	1996-1999
	Envoy	1999-2006		Trans Am	1996-2002
	Denali	1995-2006		Trans Sport	1996-1998
	Jimmy	1998-2002		Vibe	2004-2005
	Sonoma	1998-2002			
	Safari	1996-2005		SC1	1995-1999
	Savana	1999-2000		SC2	1995-1999
	Sierra	1995-2006		SL	1995-1999
THE RESERVE	Suburban	1995-2006		SL1	1995-1999
THE REAL PROPERTY.	Yukon/XL	1995-2006		SL2	1995-1999
				SW1	1995-1999
				SW2	1995-1999
The second secon					

Notes:

Buick: 1995-1999 NOT compatible with in-dash CD player.

Cadilliac, Chevrolet, GMC: 2003-2006 MUST disable factory external AV source devices. 1995-1999 NOT compatible with in-dash CD player.

1997-2004 Corvettes NOT equipped with a factory installed CD changer will need to purchase a separate cable (PXHGM4).

Oldsmobile: 2004-2005 MUST disable factory external AV source devices. 1995-2001 NOT compatible with in-dash CD player.

Particle 2004-2005 MUST disable factory external AV source devices. 1995-2001 NOT compatible with in-dash CD player.

Legal Notice:
iSimple prides itself in providing the best and most reliable electronic integration solutions available. Even after extensive research and development,


The auto manufacturer logos are trademarks and are owned by their respective companies and do not sponsor AAMP of America

HOW IT WORKS



Includes Interface, 11ft. Cable for iPod and all Harnesses required for installation









BEST SOUND POSSIBLEPlugs in Directly to Factory Radio



FULL FUNCTIONALITY Retains iPod Display and Clickwheel or touchscreen




KEEPS iPod CHARGED Ready to Go



EASY OPERATION Controls iPod Through Factory Radio





Interface




11ft. Cable for iPod



Factory radio harness

Owners Manual

COMPATIBLE WITH



YOUR DRIVE. YOUR MUSIC.

Getting a Sweet Hook Up for Your Sweet Ride is iSimple

The iSimple® SoundByte™ seamlessly integrates your iPod with the factory stereo systems in many popular 1995 - 2008 vehicle makes and models. With a SoundByte installed in your car, you'll enjoy CD-quality audio playback, basic track forward/track back control of your iPod song library through the radio, and battery charging for all your compatible iPod.





For best performance have it professionally installed.

A Division of AAMP of America™
13190 56th Court Clearwater, FL 33760
Ph. 866-788-4237
support@isimplesolutions.com
©2009 AAMP of Florida, Inc.

www.isimplesolutions.com

iPod and are trademarks of Apple Inc., registered in the U.S. and other countries.



